



Infrastructure, environment, facilities

Ms. Linda Jacobsen
U.S. Environmental Protection Agency
Region 8
1595 Wynkoop St.
Denver, CO 80202-1129

Subject:
Historic Recordation
ASARCO
East Helena Smelter Demolition

Dear Ms. Jacobsen:

Attached please find two copies of all photos taken during the recent photo documentation task at the ASARCO East Helena Smelter in JPG format. A copy of the photo log indicating the camera frame number, direction of each photo, and description of the photo is attached. A map of the camera position numbers and map correlating building locations with buildings listed on Attachment A are included. All documents are in draft format and have not been finalized.

Sincerely,

ARCADIS

Constance M. Cole
Project Manager

Copies:
Denise Kirkpatrick, DEQ, 1 copy
Josef Warhank, SHPO, 1 copy
Jon Nickel, ASARCO, 1 copy

RECEIVED
AUG 19 2008
Office of Enforcement
Compliance & Environmental
Justice

ARCADIS
1610 B Street
Suite 100
Helena
Montana 59601
Tel 406.449.7001
Fax 406.449.3063
www.arcadis-us.com

ENVIRONMENT

Date:
August 15, 2008

Contact:
Connie Cole

Phone:
406-449-7001 Ext. 13

Email:
connie.cole@arcadis-us.com

Our ref:
MH000980.0001

Imagine the result

g:\projects\mining\asarco\east helena\historic demolition recordation\communications with regulators\08-15-08 transmittal letter to epa - photos - photo log - base maps.doc

Poor Quality Source Document

The following document
images have been
scanned from the best
available source copy.

To view the actual hard copy,
contact the Region VIII Records
Center at (303) 312-6473.

Camera No.:

Prest's

Folder No.:

Camera frame #s start at 1
Data #'s start at 40.

to convert, add 39
to camera frame # or
vice versa.

Page 1 of

| Project | Frame # | Date | Initials | Direction | Site/Isolate | Feature/Artifact | Description |
|---------|---------|------|----------|-----------|------------------|------------------|---------------------------------------------|
| | 40 | 4/17 | W/AC | S-SE | Photo Position # | | Thin thin glass floor under suspended floor |
| | | | | | (see map) | | Thin floor board under suspended floor |
| | 41 | | | NE | 2 | | B.F.F. - 1st |
| | 42 | | | SE | 2 | | B.F.F. - 1st of floor (Dormitory) |
| | | | | NE | 3 | | B.F.F. underpin of brick passageway |
| | 44 | | | NE | 4 | | B.F.F. - 1st of floor w/ concrete floor |
| | 45 | | | NE | 5 | | B.F.F. - 1st of floor w/ concrete floor |
| | 46 | | | SE | 5 | | B.F.F. - 1st of floor w/ concrete floor |
| | 47 | | | SE | 6 | | B.F.F. - 1st of floor |
| | 48 | | | W-SW | 7 | | B.F.F. - 1st of floor (old floor) |
| | 49 | | | N | 7 | | B.F.F. |
| | 50 | | | N-NE | 8 | | Remains of 1st floor |
| | 51 | | | N-NE | 9 | | Base of 2nd floor |
| | 52 | | | S | 10 | | Remains of 1st floor B.F.F. at 1st of floor |
| | 53 | | | W | 10 | | Remains of 1st floor B.F.F. at 1st of floor |
| | 54 | | | NW-W | 11 | | Remains of 1st floor B.F.F. at 1st of floor |
| | 55 | | | N | 11 | | Remains of 1st floor |
| | 56 | | | N | 11 | | Remains of 1st floor |
| | 57 | | | NW | 12 | | Remains of 1st floor B.F.F. at 1st of floor |
| | 58 | | | N | 13 | | Remains of 1st floor |
| | 59 | | | E | 13 | | Acid plant |
| | 60 | | | S-SE | 13 | | B.F.F. - 1st of floor |
| | 61 | | | S-SW | 14 | | Remains of 1st floor |

Camera No.: _____

Page 2 of

Folder No.: _____

| Project | Frame | Date | Initials | Direction | Site on isolate | Feature/artifact | Description |
|---------|-------|------|----------|-----------|-----------------|------------------|------------------------------------------|
| | 62 | 7/28 | OS/PC | SW | 15 | | Steel bolt on side of engine |
| | 63 | | | SW | 15 | | " |
| | 64 | | | E | 16 | | Can house |
| | 65 | | | NE | 17 | | S. corner of engine |
| | 66 | | | N-NE | 18 | | Back of engine house (weighting place) |
| | 67 | | | E-NE | 18 | | Dis. handling with downfalls |
| | 68 | | | N | 19 | | Bulkheads in B.F.F. made of F. material |
| | 69 | | | N-NW | 20 | | Major underpass of road plant in section |
| | 70 | | | N | 21 | | Covered entrance/passageway in B.F.F. |
| | 71 | | | N-NW | 22 | | Corner of B.F.F. |
| | 72/73 | | | NE | 23 | | Exhaustor |
| | 74 | | | N | 25 | | Inside of Exhaustor |
| | 75 | | | NE | 26 | | Exhaustor interior |
| | 76 | | | NE | 27 | | Exhaustor exterior |
| | 77 | | | NE | 28 | | Exhaustor interior/corridor |
| | 78 | | | W-NW | 24 | | Back corner Exhaustor |
| | 79 | | | NW | 25 | | Buildings along exterior of B.F.F. |
| | 80 | | | W | 26 | | B.F.F. |
| | 81 | | | NW | 27 | | B.F.F. |
| | 82 | | | W | 28 | | Underpass of B.F.F. |
| | 83 | ✓ | ✓ | N-NW | 29 | | Underpass on end of B.F.F. |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |

Camera No.: _____

Page 3 of

Folder No.: Photostat 11

| Project | Frame | Date | Initials | Direction | Site or isolate | Feature/artifact | Description |
|---------|---------------|------|----------|-----------|-------------------|------------------|-----------------------------|
| 84 | 15 | 7/20 | BS/AC | N | 1 (on platform A) | | Box, 6" x 6" x 6" (approx.) |
| 85 | 16 | | | NW | 2 | | Box, 6" x 6" x 6" (approx.) |
| 86 | 17 | | | NW | 3 | | Box, 6" x 6" x 6" (approx.) |
| 87 | 18 | | | N | 4-6 | | Box, 6" x 6" x 6" (approx.) |
| 88 | 19 | | | NW | 1 | | Box, 6" x 6" x 6" (approx.) |
| 89 | 20 | | | NE | 8-11 | | Box, 6" x 6" x 6" (approx.) |
| 90 | 21 | | | N | 12-14 | | Box, 6" x 6" x 6" (approx.) |
| 91 | 22 | | | N | 15 | | Box, 6" x 6" x 6" (approx.) |
| 92 | 23 | | | N | | | Box, 6" x 6" x 6" (approx.) |
| 93 | 24 | | | N | 13-14 | | Box, 6" x 6" x 6" (approx.) |
| 94 | 25 | | | NE | 21 | | Box, 6" x 6" x 6" (approx.) |
| 95 | 26 | | | W-NW | 22 | | Box, 6" x 6" x 6" (approx.) |
| 96 | 27 | | | NW | 25 | | Box, 6" x 6" x 6" (approx.) |
| 97 | 28 | | | N-NW | 29 | | Box, 6" x 6" x 6" (approx.) |
| 98 | 29 | | | | 28 | | Box, 6" x 6" x 6" (approx.) |
| 99 | 30 | | | N-NE | 30 | | Box, 6" x 6" x 6" (approx.) |
| 100 | 31 | | | N | 1 | | Box, 6" x 6" x 6" (approx.) |
| 101 | 32 | | | N-NW | 16 | | Box, 6" x 6" x 6" (approx.) |
| 102 | 33 | | | NW | 17 | | Box, 6" x 6" x 6" (approx.) |
| 103 | 34 | | | N | 17 | | Box, 6" x 6" x 6" (approx.) |
| 104 | 35 | | | N | 18 | | Box, 6" x 6" x 6" (approx.) |
| 105 | 36 | | | N-NW | 19 | | Box, 6" x 6" x 6" (approx.) |
| 106 | 37 | | | N | 24 | | Box, 6" x 6" x 6" (approx.) |
| 107 | 38 | | | W-SW | 21 | | Box, 6" x 6" x 6" (approx.) |

Camera No.: _____

Page 4 of

Folder No.: _____

| Project | Frame | Date | Initials | Direction | Site or Isolation | Feature / Artifact | Description |
|---------|-------|------|----------|-----------|-------------------|-----------------------|------------------------------------|
| 108 | 671 | 7/15 | B. J. R. | W | 25 | | Overhead Pipe |
| 109 | 672 | | | E | 25 | | Overhead Pipe |
| 110 | 71 | | | E | 30 | | Flues entering baghouse |
| 111 | 72 | | | NE | 30 | | Steel Baghouse Walkway |
| 112 | 73 | | | NE | 30 | | Wooden Baghouse Walkway |
| 113 | 74 | | | N-NW | 31 | | Inbetween Baghouses 1 + 2 |
| 114 | 75 | | | N-NW | 31 | | " |
| 115 | 76 | | | E-SE | 31 | | Fan House / Flue |
| 116 | 77 | | | E-SE | 31 | | " |
| 117 | 78 | | | E | 32 | | Office / Control Room |
| 118 | 79 | | | E | 32 | | " |
| 119 | 80 | | | N-NW | 33 | | B/t Baghouse 2 + 3 |
| 120 | 81 | | | N-NW | 33 | | " |
| 121 | 82 | | | SW | 33 | | Looking out from Baghouse 2 |
| 122 | 83 | | | E | 33 | | Blast Furnace Area |
| 123 | 84 | | | S | 33 | | Fanhouse + Motor Flue |
| 124 | 85 | | | W | 33 | | Front of Baghouses, wooden walkway |
| 125 | 86 | | | NW | 33 | | End of Baghouse 2 |
| 126 | 87 | | | E | 33 | | Blast Furnace Area |
| 127 | 88 | | | NW | 33 | | Baghouses 1 + 2 |
| 128 | 89 | | | NW | 32 | | Interior Baghouse 2 |
| 129 | 90 | | | NW | 32 | | |
| 130 | 91 | | | NW | 32 | | |
| 131 | 92 | | | NW | 32 | | |

Camera No.: _____

Page 5 of

Folder No.: _____

| Project | Frame | Date | Initials | Direction | Site or Isolate | Feature/Artifact | Description |
|---------|---------|------|----------|-----------|-----------------|------------------|----------------------------------|
| 132 | 93 | 7/30 | BS/AC | SE | 32 | | South wall Baghouse |
| 133 | 94 | | | SE | 32 | | West wall Baghouse |
| 134 | 95 | | | W/NW | 34 | | Baghouses |
| 135 | 96 | | | SW | 34 | | Fan House |
| 136 | 97 | | | N | 34 | | Crushing Mill |
| 137 | 98 | | | E | 34 | | Acid Plant |
| 138 | 99 | | | N-NE | 34 | | Dust + Cement Storage |
| 139 | 100 | | | SW | 35 | | Back of Baghouse + Dust handling |
| 140 | 101 | | | S | 36 | | North End Baghouse 3 |
| 141 | 102 | | | S | 37 | | North End Baghouse 1 |
| 142 | 103 | | | E-SE | 38 | | Baghouse 1 |
| 143 | 104 | | | NE | 39 | | Dust Handling |
| 144 | 105 | | | E | 40 | | Fan House |
| 145 | 106 | | | E | 40 | | Fan House Roof Damage |
| 146 | 107 | | | SE | 41 | | Fan House Interior / Gelling |
| 147 | 108 | | | SE | 41 | | Interior Flue |
| 148/149 | 109-110 | | | SE E | 42 | | SW corner of Fanhouse |
| 150 | 111 | | | N | 43 | | Fanhouse |
| 151 | 112 | | | N | 43 | | Fanhouse |
| 152 | 113 | | | N | 43 | | Fanhouse |
| 153 | 114 | | | S | 44 | | Long house |
| 154 | 115 | | | NE | 45 | | Front Auto shop - Interior |
| 155 | 116 | | | NE | 45 | | " |
| 156 | 117 | | | N | 45 | | North wall Auto Shop |

Camera No.:

Page 6 of 6

Folder No.:

[illegible]

Camera No.: _____

Page _____ of _____

Folder No.: _____

Photo Position

| Project | Frame | Date | Initials | Direction | Site or Isolate | Feature/ Artifact # | Description |
|---------|-------|------|----------|-----------|-----------------|------------------------|-------------------------------------------------------------|
| 170 | 131 | | BS | NE | | 50 | Autoshop |
| 171 | 132 | | | | | | |
| 172 | 133 | | | | | | |
| 173 | 134 | | | | | | |
| 174 | 135 | | | | | | |
| 175 | 136 | | | | | | |
| 176 | 137 | | | | | | |
| 177 | 138 | | | ESE | | 40 | Fan house detail of window |
| 178 | 139 | | | E | | 40 | |
| 179 | 140 | | | N | | 40 | Air receiver (#A20) / Bathroom 1 |
| 180 | 141 | | | N | | 40 | Zoom Bathroom 1 |
| 181 | 142 | | | NNE | | 40 | Air receiver (#A20) |
| 182 | 143 | | | E | | 40 | Fan house addition |
| 183 | 144 | | | | | | |
| 184 | 145 | | | | | | |
| 185 | 146 | | | | | | |
| 186 | 147 | | | | | | |
| 187 | 148 | | | | | | |
| 188 | 149 | | | | | | |
| 189 | 150 | | | | | | |
| 190 | 151 | | | | | | |
| 191 | 152 | | | | | | |
| 192 | 153 | | | N | | | Fan house from 2nd floor downstairs |
| 193 | 154 | | | NNE | | | Fan house 2nd floor up into rafters shows flue very well |

Camera No.: _____

Page _____ of _____

Folder No.: _____

| Project | Frame | Date | Initials | Direction | Sites on solar | Feature/artifact | Description |
|---------|-------|---------|----------|-----------|--------------------------------------------|------------------|------------------------------------------------------------|
| 194 | 145 | 8/06/02 | BS | E | | FH | Fanhause 2nd floor - fan driveshaft & flue |
| 195 | 156 | | | NE | | | Fanhause 3rd floor thru rafters ^{towards} towards |
| 196 | 157 | | | E | | | FH flywheel motor 2nd floor |
| 197 | 158 | | | S | | | Thru South window - Monier flue |
| 198 | 159 | | | S | | | 1st floor up stairs |
| 199 | 160 | | | SE | | | Concrete mounts |
| 200 | 161 | | | NW | | V | 2nd floor - yard addition |
| 201 | 162 | | | N | | Baghouse 1 | BH 1 - door 2 |
| 202 | 163 | | | N | | | Baghouse arch |
| 203 | 164 | | | W/up | | BH 2 door | Bag attachments/couplings |
| 204 | 165 | | | W/up | | | " |
| 205 | 166 | | | N/up | | | |
| 206 | 167 | | | W/up | | | |
| 207 | 168 | | | N | | BH 3 door | |
| 208 | 169 | | | | | | |
| 209 | 170 | | | | | | |
| 210 | 171 | | | | | | |
| 211 | 172 | | | W | Taken at ground level just south of BH 2/3 | | of Flue #2 |
| 212 | 173 | | | W | | | |
| 213 | 174 | | | W/up | " | | " of walkway + BH! |
| 214 | 175 | | | S | | | Bag "caps" on gangway |
| 215 | 176 | | | S | | | |
| 216 | 177 | | | N | | | Fanhause south facade |
| 217 | 178 | | | N | Into BFF in front of incinerator | | |

Page of

Page of

| Project | Frame | Date | Initials | Direction | Site/isolation | Feature/artifact | Description |
|---------|-------|--------|----------|-----------|--------------------|--------------------------|-------------------------|
| 218 | 179 | 8/7/02 | B.S. | N | | | Inc. Profile |
| 219 | 180 | | | SW | Rusty top of Inc. | | from ladder at East end |
| 220 | 181 | | | E | Inc doors closed | | |
| 221 | 182 | | | ENE | BFF roof | from | Spray Dry Rd; gantry |
| 222 | 183 | | | ENE | Down onto BFF roof | | |
| 223 | 184 | | | NNW | Cottrell from " | | " |
| 224 | 185 | | | NE | Inc / BFF bend | from | " |
| 225 | 186 | | | NNW | Stack detail | from | " |
| 226 | 187 | | | NNW | Acid Plant | from | " |
| 227 | 188 | | | W | Bag House #2 | East facade | |
| 228 | 189 | | | N | " | shows Door entrance | at base North End |
| 229 | 190 | | | N | " | shows Unwatered entrance | |
| 230 | 191 | | | | Cap detail | | |
| 231 | 192 | | | NW | B.H. | South facade | |
| 232 | 193 | | | E | P.H.F. | NW facade/corner | |
| 233 | 194 | | | E | " | | |
| 234 | 195 | | | E | " | North facade | |
| 235 | 196 | | | ENE | " | West facade | |

Camera No.: _____

Page _____ of _____

Folder No.: _____

Data
#SCamera
#SAttachment "A"
Structure #'s

| Project | Frame | Date | Initials | Direction | Sits on isolate | Feature Artifact # | Description |
|---------|-------|------|----------|-----------|-----------------|---------------------------------------|-------------------------|
| 236 | 197 | | | N | | | Blacksmith Interior |
| 237 | 198 | | | N | | | |
| 238 | 199 | | | NW | | | |
| 239 | 200 | | | NE | | | |
| 240 | 201 | | | NE | | | Blacksmith Flue |
| 241 | 202 | | | E | | | North Facade Blacksmith |
| 242 | 203 | | | N | | | West Facade oblique ↓ |
| 243 | 204 | | | W | ⑥ | Paint store shed | |
| 244 | 205 | | | N | ⑥ | " " Shows shed roof, Bldg against PFF | |
| 245 | 206 | | | W | ⑥ | Interior | |
| 246 | 207 | | | WSE | ⑥ | Interior | |
| 247 | 208 | | | NW | ⑤ | Paint shop | |
| 248 | 209 | | | W | ⑤ | | |
| 249 | 210 | | | WNW | ⑤ | Int detail | |
| 250 | 211 | | | SE | ⑤ | " " | |
| 251 | 212 | | | W | ② | Pipe fitter shed ext | |
| 252 | 213 | | | W | ② | Int. | |
| 253 | 214 | | | N | ② | With ore bin | |
| 254 | 215 | | | S | ② | ext | |
| 255 | 216 | | | WSW | ③ | Blacksmith coke bins | |
| 256 | 217 | | | WNW | ③ | ↓ | |
| 257 | 218 | | | W | * | Air tank near Water Tanks | |
| 258 | 219 | | | N | ② | Bins A-D Left to Right | |
| 259 | 220 | | | W | ② | Bins E → A Right to Left | |

Camera No.: _____

Page _____ of _____

Folder No.: _____

| Project | Frame | Date | Initials | Direction | Site or isolate | Feature/Artifact | Description |
|---------|-------|--------------------|----------|-----------|-----------------|---------------------------------------|-------------------------------------|
| 260 | 221 | | | W | (4) | | Int. Carpenter Shop |
| 261 | 222 | | | S | | | " " |
| 262 | 223 | | | N | | thru doorway | Adjacent to North Insulation Shop |
| 263 | 224 | | | W | | | Insulation Shop interior |
| 264 | 225 | | | W | | | " " Rafter |
| 265 | 226 | | | W | (11) | Sand Filter Bldg | Exterior East facade |
| 266 | 227 | | | W | | " | " |
| 267 | 228 | | | N | | " | South facade exterior |
| 268 | 229 | | | W | | " | Interior-North 1/2 -w- Tank & panel |
| 269 | 230 | | | W | | " | " |
| 270 | 231 | | | W | | | " Interior-South 1/2 -w- p - on |
| 271 | 232 | | | N | (10) | Acid plant + Cooling Towers | |
| 272 | 233 | | | E | (12) | | Trailer |
| 273 | 234 | | | N | (28) | Gunnite Storage Bldg | interior |
| 274 | 235 | From East Wall - W | | W | (4) | Acid Plant Shop | "INSTRUMENT SHOP" interior |
| 275 | 236 | " " | | W | (4) | " | " |
| 276 | 237 | " " | | W | (14) | Same direction as above but UP stairs | |
| 277 | 238 | | | NW | (15) | Shop interior | |
| 278 | 239 | | | SW | | | |
| 279 | 240 | | | WSW | | | |
| 280 | 241 | | | N | | | |
| 281 | 242 | | | SE | | | |
| 282 | 243 | | | SE | | | |
| 283 | 244 | | | ENE | | | |

Camera No.: _____


Page _____ of _____

Folder No.: _____

| Project | Frame | Date | Initials | Direction | Site or Isolate | Feature/Artifact | Description |
|---------|-------|------|----------|-----------|-----------------|-------------------|-------------------------|
| 284 | 245 | | | N | (14) | Acid Plant Shop | South facade |
| 285 | 246 | | | W | | | East facade |
| 286 | 247 | | | S | | | North facade |
| 287 | 248 | | | W | (13) | Instrument shed | East facade |
| 288 | 249 | | | W | | | Interior |
| 289 | 250 | | | W | (15) | Acid Plant Shop | Interior left |
| 290 | 251 | | | W | | | Interior right |
| 291 | 252 | | | W | | | East facade |
| 292 | 253 | | | E | (20) | Art Receiver Tank | |
| 293 | 254 | | | S | | Blksmith int | |
| 294 | 255 | | | W | (27) | Lamp Tank | |
| 295 | 256 | | | W | | Interior | |
| 296 | 257 | | | W | | Exterior | |
| 297 | 258 | | | N | | Inside | |
| 298 | 259 | | | NE | (29) | Weak acid Pipe | |
| 299 | 260 | | | SE | (30) | Slender Tank | from North side |
| 300 | 261 | | | W | (31) | Overhead pipe | Prom. from by Auto shop |
| 301 | 262 | | | E | (17) | Overhead pipe | |
| 302 | 263 | | | WSW | (17) | | |
| 303 | 264 | | | E | | Acid Plant closer | |
| 304 | 265 | | | | (23) | Exp. mon. stat. | from Gantry |
| 305 | 266 | | | SE | (24) | Over. Vent Pipe | from Gantry |
| 306 | 267 | | | E | (21) | Exp. mon. stat. | from Gantry |
| 307 | 268 | | | | | Storage tank | from Gantry |

Folder No.:

[illegible]



Camera
Position
#'s

| | | |
|-------------------------------------------------------------------------------------------------------------------------|-----------------------------|---------------|
| BLAST FURNACE FLUE & MONIER FLUE CLEANING AND DEMOLITION AND DEMOLITION FOOT PRINT EXPOSED AREAS SOIL SAMPLING | PROPOSED 2008 TEMPORARY CAP | FIGURE 2-4 |
|-------------------------------------------------------------------------------------------------------------------------|-----------------------------|---------------|


Attachment A

Pictures have been taken of ALL these structures/facilities.

Adjacent or adjoining structures that are likely to be affected by cleaning and demolition (see Figure A.1)

1. Blast furnace cooling water return tanks- These provided the blast furnaces with a source of constantly circulating water to cool the jacket walls. The ones here, painted blue, are relatively modern. No real ASARCO data found. **Photographed and measured**
2. Pipefitter storage shed- Probably 1960's in origin? No ASARCO plans or data found **Photographed and floor plan drawn**
3. blacksmith coke storage bin-Very little or no ASARCO data to find for these type of things **Photographed and floor plan drawn**
4. carpenter shop- 1949 with additions from the 1960's, **Four ASARCO plan drawings pulled for digitizing**
5. former paint shop-No ASARCO data found **Photographed and floor plan drawn**
6. former paint storage shed-No ASARCO data found **Photographed and floor plan drawn**
7. incinerator-No ASARCO data, **Thoroughly photo-documented, field notes taken**
8. spray drier building with fan and stack-Brand new, never used **Engineer plans pulled, Photographed**
9. truck unloading building-Brand new, never used **Engineer plans pulled, Photographed**
10. Acid plant cooling towers with chemical storage tanks-Acid plant is Mid-1970s, **one ASARCO plan pulled for digitizing; some plans may still be in Engineering building. Photographed**
11. sand filter building-New **Photographed and floor plan drawn**
12. contractor trailer- New **Photographed and measured**
13. instrument storage shed-No ASARCO data found **Photographed and floor plan drawn**
14. acid plant shop- No ASARCO data found **Photographed and floor plan drawn**
15. acid plant oil shed- No ASARCO data found **Photographed and floor plan drawn**
16. acid decolorization building with sump- 1980s **Engineer plans pulled, Photographed and notes**
17. overhead acid pipe rack from Monier flue to pump tank building-1970s **Photographed and notes**
18. Ringling dust building-New **To be dismantled and moved. Call Helena Insulation re: Coverall Bldgs. 406-443 4353**
19. lime storage building- **At least one ASARCO drawing pulled, Photographed**
20. air receiver- Old, but no real ASARCO data found **Photographed and measured**
21. dust handling system with baghouse-1980s **Engineer plans pulled, Photographed**
22. overhead ventilation pipe 1980s **Photographed and notes**
23. emission monitoring station with support/stack fan- 1980s **Engineer plans pulled, Photographed**
24. overhead dust handling pneumatic transfer pipe-1980s **Photographed and notes**
25. ore storage bins- No ASARCO data found **Photographed and measuring notes**
26. auto shop-Cottrell building, 1917, **Original engineer plans pulled, Floor plan drawn in field with notes of building revisions**
27. pump tank building sump-Mid-1970s **Engineer plans pulled, Photographed**
28. former gunnite storage building- No ASARCO data found **Photographed and measured**
29. weak gas handling flue-Mid-1970s **Photographed and notes**
30. sinter stack fan-1980s **Engineer plans pulled, Photographed**

Attachment
"A"



TARGET SHEET
EPA REGION VIII
SUPERFUND DOCUMENT MANAGEMENT SYSTEM

DOCUMENT NUMBER: 1075788

SITE NAME: EAST HELENA RCRA CORRECTIVE ACTION

DOCUMENT DATE: 08/15/2008

DOCUMENT NOT SCANNED

Due to one of the following reasons:

- ☐ PHOTOGRAPHS
- ☐ 3-DIMENSIONAL
- ☐ OVERSIZED
- ☒ AUDIO/VISUAL
- ☐ PERMANENTLY BOUND DOCUMENTS
- ☐ POOR LEGIBILITY
- ☐ OTHER
- ☐ NOT AVAILABLE
- ☐ TYPES OF DOCUMENTS NOT TO BE SCANNED
(Data Packages, Data Validation, Sampling Data, CBI, Chain of Custody)

DOCUMENT DESCRIPTION:

2 CDs - PHOTO DOCUMENTATION, DISKS 1 AND 2

Page 1 of 1

From: Origin ID: HLNA (406)449-7001
 Keith Smith
 ARCADIS
 1610 B STREET

HELENA, MT 59601




CL563388 8/2 1/24

SHIP TO: 3033126503

BILL THIRD PARTY

Linda Jacobsen
 Environmental Protection Agency
 Region 8
 1595 Wynkoop St.
 Denver, CO 802021129



Ship Date: 18AUG08
 ActWgt: 1 LB
 System#: 2759753/INET8061
 Account#: S *****

Delivery Address Bar Code



Ref # MH000980.0001
 Invoice #
 PO #
 Dept #

EIF

TRK# 7984 9723 1500
 0201

TUE - 19AUG A1
 FIRST OVERNIGHT

X1 TEXA

80202
 CO-US
 DEN



Shipments Only